## § 90.710

production line testing program was conducted in complete conformance with all applicable regulations under 40 CFR Part 90. No emission-related changes to production processes or quality control procedures for the engine family tested have been made during this production line testing program that affect engines from the production line. All data and information reported herein is, to the best of (Company Name) knowledge, true and accurate. I am aware of the penalties associated with violations of the Clean Air Act and the regulations thereunder. (Authorized Company Representative.)

## § 90.710 Compliance with criteria for production line testing.

- (a) A failed engine is one whose final deteriorated test results pursuant to \$90.709(c), for  $HC+NO_X$  (NMHC+NO<sub>X</sub>) or CO exceeds the applicable Family Emission Limit (FEL) or standard if no FEL.
- (b) An engine family shall be determined to be in noncompliance, if at any time throughout the model year, the CumSum statistic,  $C_{\rm i}$ , for HC+NO<sub>X</sub> (NMHC+NO<sub>X</sub>) or CO, is greater than the action limit, H, for that pollutant, for two consecutive tests.

## § 90.711 Suspension and revocation of certificates of conformity.

- (a) The certificate of conformity is suspended with respect to any engine failing pursuant to §90.710(a) effective from the time that testing of that engine is completed.
- (b) The Administrator may suspend the certificate of conformity for an engine family which is determined to be pursuant noncompliance §90.710(b). This suspension will not occur before thirty days after the engine family is determined to be in noncompliance and the Administrator has notified the manufacturer of its intent to suspend. During this thirty day period the Administrator will work with the manufacturer to achieve appropriate production line changes to avoid the need to halt engine production, if possible. The Administrator will approve or disapprove any such production line changes proposed to address a family that has been determined to be in noncompliance under this subpart within 15 days of receipt. If the Administrator does not approve or disapprove such a proposed change within such

time period, the proposed change shall be considered approved.

- (c) If the results of testing pursuant to the regulations in this subpart indicate that engines of a particular family produced at one plant of a manufacturer do not conform to the regulations in this part with respect to which the certificate of conformity was issued, the Administrator may suspend the certificate of conformity with respect to that family for engines manufactured by the manufacturer at all other plants.
- (d) Notwithstanding the fact that engines described in the application for certification may be covered by a certificate of conformity, the Administrator may suspend such certificate immediately in whole or in part if the Administrator finds any one of the following infractions to be substantial:
- (1) The manufacturer refuses to comply with any of the requirements of this subpart.
- (2) The manufacturer submits false or incomplete information in any report or information provided to the Administrator under this subpart.
- (3) The manufacturer renders inaccurate any test data submitted under this subpart.
- (4) An EPA enforcement officer is denied the opportunity to conduct activities authorized in this subpart and a warrant or court order is presented to the manufacturer or the party in charge of the facility in question.
- (5) An EPA enforcement officer is unable to conduct activities authorized in §90.705 because a manufacturer has located its facility in a foreign jurisdiction where local law prohibits those activities.
- (e) The Administrator shall notify the manufacturer in writing of any suspension or revocation of a certificate of conformity in whole or in part, except that the certificate is immediately suspended with respect to any failed engines as provided for in paragraph (a) of this section.
- (f) The Administrator may revoke a certificate of conformity for an engine family after the certificate has been suspended pursuant to paragraph (b) or (c) of this section if the proposed remedy for the nonconformity, as reported